


100

**FIG. 1**






FIG. 3

**FIG. 4**




FIG. 5

	W ₁ X ₁	W ₁ X ₂	W ₁ X ₃	W ₂ X ₁	W ₂ X ₂	W ₂ X ₃	W ₃ X ₁	W ₃ X ₂	W ₃ X ₃
W ₁ X ₁	601	0	0	0	0	0	0	0	0
W ₁ X ₂	602	603	0	0	0	0	0	0	0
W ₁ X ₃	0	604	605	0	0	0	0	0	0
W ₂ X ₁	606	0	0	607	0	0	0	0	0
W ₂ X ₂	608	609	0	610	611	0	0	0	0
W ₂ X ₃	0	612	613	0	614	615	0	0	0
W ₃ X ₁	0	0	0	616	0	0	617	0	0
W ₃ X ₂	0	0	0	618	619	0	620	621	0
W ₃ X ₃	0	0	0	0	622	623	0	624	625

FIG. 6

600




FIG. 7




FIG. 8

	W ₁ X ₁	W ₁ X ₂	W ₁ X ₃	W ₂ X ₁	W ₂ X ₂	W ₂ X ₃	W ₃ X ₁	W ₃ X ₂	W ₃ X ₃	W ₄ X ₁	W ₄ X ₂	W ₄ X ₃	
W ₁ X ₁	<u>701</u>	0	0	0	0	0	0	0	0	0	0	0	r ₁
W ₁ X ₂	<u>702</u>	<u>703</u>	0	0	0	0	0	0	0	0	0	0	r ₂
W ₁ X ₃	0	<u>704</u>	<u>705</u>	0	0	0	0	0	0	0	0	0	r ₃
W ₂ X ₁	<u>706</u>	0	0	<u>707</u>	0	0	0	0	0	0	0	0	r ₄
W ₂ X ₂	<u>708</u>	<u>709</u>	0	710	<u>711</u>	0	0	0	0	0	0	0	r ₅
W ₂ X ₃	0	<u>712</u>	<u>713</u>	0	<u>714</u>	<u>715</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	<u>0</u>	r ₆
W ₃ X ₁	0	0	<u>716</u>	0	0	0	<u>717</u>	0	0	0	0	0	r ₇
W ₃ X ₂	0	0	<u>718</u>	<u>719</u>	0	0	<u>720</u>	<u>721</u>	0	0	0	0	r ₈
W ₃ X ₃	0	0	0	0	<u>722</u>	<u>723</u>	0	<u>724</u>	<u>725</u>	0	0	0	r ₉
W ₄ X ₁	0	0	0	0	0	0	<u>1001</u>	0	0	<u>1002</u>	0	0	r ₁₀
W ₄ X ₂	0	0	0	0	0	0	<u>1003</u>	0	<u>1004</u>	0	<u>1005</u>	0	r ₁₁
W ₄ X ₃	0	0	0	0	0	0	0	<u>1007</u>	<u>1008</u>	0	<u>1009</u>	<u>1010</u>	r ₁₂

600

900

FIG. 9




FIG. 10